### D7 El Faro Initial Position Report



Paul Webb Search and Rescue Specialist, CGD17

#### 011113Z InmarsatPosition Reports


- Command Duty Officer at Atlantic Area Command Center received two reports of distress for the EL FARO that were passed to RCC Miami. The report from Inmarsat C Alert received (01115Z) and CAPT John Lawrence (011124Z), TOTE Security Officer.
- The LANTWATCH email to RCC Miami stated the position information as follows:
  - "We received the below Inmarsat C distress alert from M/V EL FARO in position 23.28N 73.48W for flooding distress."
  - "The Command Security Officer for the vessel company contacted the vessel and relayed their condition to us, POC John Lawrence, #1 ( 23-26.3N 073-51.6W, 48NM Fact of San Salador "
- Attached to that email was the "Distress Information Sheet" from Marlink.com that showed the following position:
  - 23.28N 73.48W
- SSAS Position received at 011115Z by LANTAREA CC.
  - LAT: 23:25.39N LON: 073:52.51W
- Initial Notification in RCC Miami's MISLE States: "Initial Notification D7 received and Inmarsat C alert a SASS alert and an unlocated first alert for the EPIRB registered to EL FARO a 791FT Cargo vessel located 36NM NE Acklins & Crooked Islands, BS. D7 notified OPBAT (Operation Bahamas, Turks and Caicos) who NTFD (notified) RBDF (Royal Bahamian Defense Forces)."
- OPBAT Notification MILSE Entry: D7 OPBAT of a 791ft US flagged cargo vessel in position 23-16.8N 073-28.8W or 16NM NE of Samana Cay took on water which caused its engines to stop. They dewatered the vessel, but are currently disable and have no power. Vessel is currently working with company to get tow assistance.

#### **SAROPS Position Conversion**


- The USCG Search and Rescue Optimal Planning System (SAROPS)
  can covert different formats including; DD.DD, DD-MM-SS to DDMM.mm, which is the standard format recognized for Latitude and
  Longitude and is preferred for navigation and SAR planning.
- SAROPS cannot convert or display positions as DD.MM' or DD:MM.mm. An error is given stating that there are too many characters. The SAROPS operator must convert those positions manually before entering into SAROPS.
- SAROPS saw the 23.28N 073.48W position as DD.DD vice DD.MM and converted the position to 23-16.8N 073-28.8W.
- Positions available to the Coast Guard for the El Faro LKP were:
  - Inmarsat C Distress Alert Received Message: 23.28'N 73.48'W
  - Inmarsat C Distress Information Sheet: 23.28N 73.48W (Will convert to the incorrect position 23-16.8N 073-28.8W)
  - CAPT Lawrence Report to the Coast Guard: 23-26.3N 073-51.6W
  - SSAS Alert Message: LAT: 23:25.39N LON: 073:52.51W

#### **Initial Position SAROPS Entry**

Unable to Convert DD.MM'N




Able to Convert DD.DDN to DD-MM.mmN




Resulted in D7 CC Watch initially using wrong location for El Faro.

#### Initial Position Report Discrepancies



## USCG MISLE Entries Initial Notification and Notification of OPBAT

MISLE Activity Id	Start Date/Time	Unit	Message/Description	Location
5734211	01OCT2015 11:47:41Z	ОРВАТ	D7 OPBAT of a 791ft US flagged cargo vessel in position 23-16.8N 073-28.8W or 16NM NE of Samana Cay took on water which caused its engines to stop. They dewatered the vessel, but are currently disable and have no power. Vessel is currently working with company to get tow assistance.	
5733198	01OCT2015 11:58:47Z	D07 dr	Initial Notification - D7 recieved and Inmarsat C alert a SASS alert and an unlocated first alert for the EPIRB regestered to EL FARO a 791FT Cargo vessel located 36NM NE Acklins & Crooked Islands, BS. D7 notified OPBAT who NTFD RBDF.	



### Initial SAR Check Sheet and LANT Area Email to RCC Miami


SEARCH AND RI	ESCUE Date/Time				
Short Title: MN EL FARU /U					
Watchstander: 057					
INITIAL INFORMATION COLLECTION - AWAREN	NESS Appendix G to COMDTINST M16130.2E				
Radio Call Frequency: 406 High S	ite: DF Bearing:				
Type of Comms: DSC/INNC/EPERB Origina	Relay FM: LANT				
Time: 1/337 Date: 01 007/5 UCN:	Initials:				
Initial SAR Check Sheet					
	Type of [ ] Lat/Long [ ] Loran Lines [ ] Geographic Reference				
2. Number of Persons On Board Adults: 25	Children: Total:				
3. Nature of Distress (if PIW complete additional PIW box below) DISABLED:					
4. Description of Vessel Name: £L FAVEO Length: 791  Make: CARG-O Color: WMF/13CU  Type: CARG-O					
5. Have all persons on board the vessel put on Personal Flotation Devices / adequate number of PFD's available? Y/N					
** ADVISE REPORTING SOURCE OF INTENDED ACTIONS AT THIS TIME **					
6. Determine Initial Severity / Emergency Phase					
[ ] Distress [ ] Dispatch Resources / Activate SAR Alarm [ ] Advise reporting source of Coast Guard's Actions [ ] Issue Urgent Marine Information Broadcast (UMIB) [ ] Brief Sector / District [ ] Provide emergency instructions to vessel in distress [ ] Complete additional check-sheets as situation dictates	Additional information is needed Complete one or more of the following:  [ ] Supplemental Check-sheet [ ] Overdue Check-sheet [ ] Flare Sighting Check-sheet [ ] MEDEVACIMEDICO Check-sheet [ ] Grounding Check-sheet [ ] Mass Rescue Operation Supplemental Check-sheet				

From: D07-SMB-CMDCENTER LANTWATCH; SAT EIKVAKT (Marlink) Inmarsat C distress: Distress info EL FARO, 48NM East of San Salvador Date: Thursday, October 01, 2015 7:32:41 AM Attachments: image001.png RCC Miami. We received the below Inmarsat C distress alert from M/V EL FARO in position 23.28N 73.48W for flooding MISLE reports it is a 737 foot vessel. The vessel also activated it's SSAS alarm. The Command Security Officer for the vessel company contacted the vessel and relayed their condition to us, POC John Lawrence, #1 ( The vessel is in position 23-26.3N 073-51.6W, 48NM East of San Salador. A scuttle opened in rough weather and the vessel took on water creating a 15 degree list. They stopped the ingress of water and are not at risk of sinking, but they are without power and engines. They are dewatering the vessel. Please assume SMC and work with RCC Bahamas to respond and report back on your efforts. Command Duty Officer USCG Atlantic Area Command Center Warning: This document is FOR OFFICIAL USE ONLY (FOUO). It is to be controlled, stored, handled, transmitted, distributed, and disposed of in accordance with Coast Guard and DHS policy relating to FOUO

B-25

Appendix B: National Standard

# Inmarsat C Distress Informatio Sheet Received by RCC Miami




STEINAR JOHANNESEN REMARKS:

## SSAS Report Received by LANTAREA Not Transmitted to RCC Miami

----Original Message-----From: [mailto: Sent: Thursday, October 01, 2015 7:15 AM To: D11-DG-SSAS Subject: SSAS ALERT REPORT 2 --- SSAS ALFRT MFSSAGF ---Vessel Name: EL FARO MMSI: IMN: LAT: 23:25.39N LON: 073:52.51W Time: 10/01/2015 11:13:49(UTC) COURSE: 214 deg SPEED: 04 kt

Time: 10/01/2015 11:13:49(UTC)

#### From CAPT Lawrence's Notes



# Enhanced Group Call SAR Messaged Drafted by RCC Miami

